


Comset 3G/4G/5G Router Firmware Upgrade Procedure

Important: Update the firmware via local network with a LAN cable directly connected to your PC.

A. Comset CM210Q-W, CM510Q-W and CM550W

1. Save the new firmware on your PC.
2. Navigate to Administration > Upgrade.
3. Click on "Browse" and select the firmware file.
4. Click "Upgrade". See screenshot below.
5. Wait 3-5 minutes for the modem to initialise and synchronise with the network.
6. Login to check the status page.



B. Comset CM685V, CM820V, CM770W and CM950W

1. Save the new firmware on your PC.
2. Navigate to System > Upgrade.
3. Click on "Browse" and select the firmware file.
4. Click "Upload image" then confirm. See screenshot below.
5. Wait 3-5 minutes for the modem to initialise and synchronise with the network.
6. Login to check the status page.

Note: Uncheck "keep Settings" to get the router to factory default.

